

Generalized characteristic of the bridge and its reconstruction

1. Name of the Project **Za Černým mostem Y502, Praha 9, č. akce 999639**
2. Description of the key works of the reconstruction
 - Creation of the 'zero section' on the railway track and provisional pedestrian bridge
 - Removal of bridge accessories, demolish the superstructure, abutments and retaining walls
 - Build new retaining walls and abutments, refurbishment of the part of the abutments which are kept intact
 - Installation of precast beams of the superstructure, cast the composite concrete deck
 - Install expansion joints and remaining accessories incl. the pavement on the area neighbouring to the bridge
3. Year of construction 1978
4. The last reconstruction: No previous reconstruction
5. History of previous repairs:
 - a. years:
 - 2016,
 - 2017,
 - 2018
 - b. short description of repair works
 - repair of footways and waterproofing in 2016,
 - production and installation of staircase, painting of protection meshes and handrails 2017,
 - overall cleaning, removal of growing vegetation, removal and repair of road pavement, mastix added 2018
 - c. financial costs of the repair (excl. VAT)
 - 181 105,20 in 2016
 - 266 376,50 in 2017
 - 363 668,40 in 2018
6. Main characteristics of the bridge:
 - a. type of structure single span bridge from precast prestressed concrete beams, abutments with spread footing
 - b. road pavement surface asphalt concrete
 - c. footways surface in situ reinforced concrete
 - d. number of spans 1
 - e. superstructure supports elastomeric bearings
 - f. spanned obstacle 3-track railway line Praha Hlavní nádraží - Turnov v žkm : 10,800 - 10,900 and Lysá nad Labem - Praha Vysočany v žkm: 24,800 – 24,900
 - g. free width of the bridge 12,5 m; 11,3 m
 - h. superstructure length and bridged length 30,5 m; 43,0 m
 - i. height (of bridge, free, construction) 8,4 m; min. 6,577 m; 1,86 m

- j. substructure material massive plain concrete abutments concrete B135, abutment top from reinforced concrete C 30/37-XF4
- k. superstructure material beams C 45/55-XF2, deck C30/37-XF2
- l. drainage transverse and longitudinal slope into the gullies behind the bridge
- m. networks public lighting
- n. waterproofing bitumenous heat-glued stripes
- o. noise barriers none
- p. carrying capacity to be calculated after the bridge is finished; expected minimum values are $V_n=32t$; $V_r=80t$; $V_e=180t$ acc. to ČSN EN 73 6222 zm. Z1
- q. traffic on the bridge:
- public mass transport on rails (ANO/NE) No
 - public mass transport other (ANO/NE) Yes
 - IAD (ANO/NE) ANO
 - Separate cycling path No
 - Footways Yes
 - Number of lanes 1+1

7. State of the bridge:

- a. substructure IV. – very poor
- b. superstructure IV. – very poor
- c. diagnostics results (short description)

For description of the status of the structure see:

Diagnostics inspection of the bridge, Kaplan Tomáš, Ing., Pontex spol. s r. o., 04/2017

The complete bridge diagnostics is included as an attachment.

8. Photos of side of the bridge and of space on the bridge



Obr. 1 - Side view



Obr. 2 – Arrangement on the bridge